

DrillChem Explosion and Fire

Photo Log

Description: Frac tank used for temporary storage of run-off pumped from secondary containment area.

Category: Site Photo

Latitude: 30.3158194444444

Date Taken: 8/16/2015

Longitude: -95.4014138888889

Tags:



Description: View of culvert and area of excavated soil located in ROW.

Category: Site Photo

Latitude: 30.3154805555556

Date Taken: 8/15/2015

Longitude: -95.4006888888889

Tags:



Description: Roll-off boxes containing soil excavated from ROW staged on-site.

Category: Site Photo

Latitude: 30.3179583333333

Date Taken: 8/16/2015

Longitude: -95.4011527777778

Tags:



Description: Overview of site taken from Hwy 336 overpass.

Category: Site Photo

Latitude: 30.3175527777778

Date Taken: 8/15/2015

Longitude: -95.4008722222222

Tags:



Description: EPA, TCEQ and Conroe FD representatives

Category: Site Photo

Latitude: 30.3169

Date Taken: 8/15/2015

Longitude: -95.4021

Tags:



DrillChem Explosion and Fire

Photo Log

Description: Area of excavated soil located within the right of way.

Category: Site Photo

Latitude: 30.3157055555556

Date Taken: 8/15/2015

Longitude: -95.4006416666667

Tags:



Description: Product and water removal from surface impoundment.

Category: Site Photo

Latitude: 30.3154861111111

Date Taken: 8/15/2015

Longitude: -95.4009861111111

Tags:



Description: Metal debris of the northern structure destroyed in the fire.

Category: Site Photo

Latitude: 30.3168

Date Taken: 8/15/2015

Longitude: -95.4022361111111

Tags:



Description: Second 210 barrel tank.

Category: Site Photo

Latitude: 30.3184861111111

Date Taken: 8/15/2015

Longitude: -95.4018027777778

Tags:



Description: 500 barrel and 210 barrel tanks. A third 210 barrel tank destroyed in the fire. No contents in the tanks reported by the RP.

Category: Site Photo

Latitude: 30.31685

Date Taken: 8/15/2015

Longitude: -95.4017555555556

Tags:



DrillChem Explosion and Fire

Photo Log

Description: View inside of southern most structure.

Category: Site Photo

Latitude: 30.3164666666667

Date Taken: 8/15/2015

Longitude: -95.4018027777778

Tags:



Description: Remains of the northern most site structure.

Category: Site Photo

Latitude: 30.3167333333333

Date Taken: 8/15/2015

Longitude: -95.4017555555556

Tags:



Description:

Category: Site Photo

Latitude: 30.3164888888889

Date Taken: 8/15/2015

Longitude: -95.4018388888889

Tags:



Description: View of the surface impoundment and collection area for product runoff.

Category: Site Photo

Latitude: 30.3165083333333

Date Taken: 8/15/2015

Longitude: -95.4014972222222

Tags:



Description: View of facility looking west.

Category: Site Photo

Latitude: 30.3163583333333

Date Taken: 8/15/2015

Longitude: -95.40145

Tags:



DrillChem Explosion and Fire

Photo Log

Description: View of the facility looking north.

Category: Site Photo

Latitude: 30.316125

Date Taken: 8/15/2015

Longitude: -95.4013361111111

Tags:



Description: Drainage channel located on the west side of the site.

Category: Site Photo

Latitude: 30.3162722222222

Date Taken: 8/15/2015

Longitude: -95.4020472222222

Tags:



Description: North view of the drainage channel located on the west side of the site.

Category: Site Photo

Latitude: 30.3162722222222

Date Taken: 8/15/2015

Longitude: -95.4020472222222

Tags:



Description:

Drainage channel containing product located along the west side of the site.

Category: Site Photo

Latitude: 30.3159583333333

Date Taken: 8/15/2015

Longitude: -95.4020083333333

Tags:



Description: Surface Impoundment located on the south side of the site.

Category: Site Photo

Latitude: 30.316125

Date Taken: 8/15/2015





Longitude: -95.4011472222222

Tags:



DrillChem Explosion and Fire

Photo Log

Description: Aerial View Showing Commercial/Industrial/Residential Areas			
Category:	Google Earth Photos	Latitude:	
Date Taken:		Longitude:	
Tags:			
Description: Aerial View of Facility Location			
Category:	Google Earth Photos	Latitude:	
Date Taken:		Longitude:	
Tags:			
Description: Conroe View Showing Facility Location			
Category:	Google Earth Photos	Latitude:	
Date Taken:		Longitude:	
Tags:			
Description: Road View of Facility			
Category:	Google Earth Photos	Latitude:	
Date Taken:		Longitude:	
Tags:			